

Certificate Of Conformity

BORY


No.: BAC240690137S02

Applicant.....: Guangdong Meite Mechanical Co., Ltd
Address.....: No.10, Shunjing Street, Hegui Industrial Park (B), Lishui Town, Nanhai District, Foshan, Guangdong, China 528241
Manufacturer.....: Guangdong Meite Mechanical Co., Ltd
Address.....: No.10, Shunjing Street, Hegui Industrial Park (B), Lishui Town, Nanhai District, Foshan, Guangdong, China 528241
Trade mark.....: N/A
Product.....: AIR NAILER, AIR STAPLER
Model(s): See the APPENDIX
Directives.....: Machinery 2006/42/EC
Standards.....: EN ISO 11148-13:2018
EN ISO 12100:2010
Report No.: B2406TR90137S02

Remark:

The certification is only valid for the equipment and configuration described, in conjunction with the test data detailed above.

The CE mark as shown beside can be used, under the responsibility of the manufacturer, after completion of an EC Directive of Conformity and compliance with all relevant EC Directive.



Approved by/Date:



Shenzhen Bory Technology Service Co., Ltd.

Tel: +86 755 2328 6925
Fax: +86 755 2328 6935
Email: Service@bory.biz
http: www.bory.biz

1/F., Building 4, Tiankou Industrial Park,
HuangtianCommunity, Hangcheng
Street, Bao'an District, Shenzhen,
Guangdong, China

Certificate Of Conformity

BORY

APPENDIX:

F30, F32, F32D, F32E, MTF32, F50G, F50E, F50D, F50H, F50C, F50J, T64A, T64B, T50SA, T50SA-B, T50MA, T50SB, T50MC, T50MB, FST50, FST50B, ST38, STC38, ST38L, ST64, ST64E, ST64D, ST64L, CS3025, MTCS2840, MTCS3040, MTCS3040L, CS3040LB, MT-G38, MT-G38H, HB3515, HB3518, ADCS-19, ADCS-22, ADCS-19-35Y, ADCS-22-35Y, RATA-19, RAIA-19, RASA-19, MFS50, TH-1213F, CN45R, CN55, CN55B, CN55K, CN55C, CN65B, CN65, CN65S, CN70B, CN70C, CN70E, CN70DS, CN70-ATS, CN80B, CN80DS, CN80E, CN90, CN90B, CN100B, CN100, CN100C, CN100EPAL, CN100DS, CN130, CN452S, CN38, SN2183F, SN2183FA, CN83F, SN3483F, SN34100, SF13021, DA6434, AP38, T50SC, T50SC-B, NP55, NP70, NP45, NP50, SC760B, SC760C, SC760S, SC712, SC7C, SC7C-I2, SC7C-P, SC7E, SC7E-I2, SC7E-P, SC77XE, MTC560, MTC600, MTHC45, C1212, C1513, C1713, C2425, C2427, C2437, C2428, C2438, P515, P515B, HM515, HF18, V1015B, V1015C, ZN0630, ZN0750, ZN0860, ZN0960, ZN1080, ZN1170, ZN1230, ZN1400, ZN1620, ZN1820, ZN2030, ZN2530, ZN2830, ZN3030, ZN0630B, ZN0750B, ZN0860B, ZN0960B, ZN1080B, ZN1170B, ZN1230B, ZN1400B, ZN1620B, ZN1820B, ZN2030B, ZN2130B, ZN2530B, ZN2830B, ZN3030B, ZN-12, ZN-12S, ZN-16, SN55, SN55B, SN80, SN80B, SN100, SN100B, SN130, SN130B, SN180, SN180B, MT-DK50, DK6015, DK7015, DK7530, DC1713, DC2415, DC2418, BW120, SM73, SM11, WS2513, WS1315, DN0626, PB30, S1313R, S1213, P88U, P88U-B, M66L, M65L, M66B, M65B, M46B, M45, M66LB, M65LB, M66B2, M65B2, M65C2, M45B2, M45C2, M45D, M45L, M45LB, M46L, M46LB, M66C, M46C3, M66C3, M46C2, M66L2, M46L2, M66C2, M66D, M85, M87, M88, M85L, M87L, M88L, P616, MP622, P622C, MP622B, P625B, P630C, MP630, MP630B, MP635, MP635B, MP650, MP650B, MT840, MT850, MT7116, MT7116S, MT7116LN, 7116, 7116BP, 7116C, 7116B, MT7105, MT8016, MT8016S, MT8016LN, MT8416, 8016D, 8016F2, 8016B, 8016E, MTP8016, MTP5016, MT5016, MT5016S, MT5016SLN, 425K, 425KB, 425KL, 1416, 1416B, MT1416, MT425J, MT425JB, 422JSM, 422J, 422J-GM2, 422JL, 1006J, 1022J, 1013J, 1013JC, 1013JD, 1013JL, 1006F, 1010F, 1022JB, MT1025J, MT1016J, MT1016JS, SJK314, 1013J-A, 1013J-AL, 8016-A, 8016-AL, 7116-A, 7116-AL, 406J, 413J, MT1016F, MT1016JLN, MT1016FLN, 1010FL, 8016BL, MT1016FS, 425KC, MT432KLM, MT432KLM-B, 432K, 438K, 440K, 440KC, 440KB, 440KE, MT440KLM, 9240B, 9240C, 635TR, 1440, 1450, MT-N851-H, MT-N851-H2, N851-L, N851F, N851, N851G, N851D, MTN851, N819, N838, PW2638-L, PW2638-LB, PW2650-L, PW2538-L, PW2538, PW2638, M45C, M46C, M65C.

Shenzhen Bory Technology Service Co., Ltd.

Tel: +86 755 2328 6925
Fax: +86 755 2328 6935
Email: Service@bory.biz
http: www.bory.biz

1/F., Building 4, Tiankou Industrial Park,
HuangtianCommunity, Hangcheng
Street, Bao'an District, Shenzhen,
Guangdong, China