

































































































S. N	Part. No	Description	Pphoto	Qty
	R32015800101	450pounds Zerowall 158-0		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585000	Rotary square tube-0/12.7*463.6		1
4	R24101587400	158Torque tube-0/Φ 22*357		1
5	R24101587200	158Stabilizing tube-0/Φ 22*340.2		1
6	R24101587401	158Torque tube/Φ 22*382.4		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator-L		1
11	R21301582000	158Activator-R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007600	Bottom linkage-0-Φ 22*387.4		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1

















S. N	Part. No	Description	Pphoto	Qty
	R32015801101	450pounds Zerowall 158-1		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585001	Rotary square tube-1/12.7*489		1
4	R24101587401	158Torque tube-1/Φ 22*382.4		1
5	R24101587201	158Stabilizing tube-1/Φ 22*365.6		1
6	R24101587402	158Torque tube/Φ 22*407.8		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator-L		1
11	R21301582000	158Activator-R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007601	Bottom linkage-1-Φ 22*412.8		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1

















S. N	Part. No	Description	Pthoto	Qty
	R32015802101	450pounds Zerowall 158-2		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585002	Rotary square tube-2/12.7*514.4		1
4	R24101587402	158Torque tube-2/Φ 22*407.8		1
5	R24101587202	158Stabilizing tube-2/Φ 22*391		1
6	R24101587403	158Torque tube/Φ 22*433.2		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator—L		1
11	R21301582000	158Activator—R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007602	Bottom linkage-2-Φ 22*438.15		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1

















S. N	Part. No	Description	Pthoto	Qty
	R32015803101	450pounds Zerowall 158-3		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585003	Rotary square tube-3/12.7*539.8		1
4	R24101587403	158Torque tube-3/Φ 22*433.2		1
5	R24101587203	158Stabilizing tube-3/Φ 22*416.4		1
6	R24101587404	158Torque tube/Φ 22*458.6		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator—L		1
11	R21301582000	158Activator—R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007604	Bottom linkage-3-Φ 22*463.4		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1

















S. N	Part. No	Description	Pthoto	Qty
	R32015804101	450pounds Zerowall 158-4		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585004	Rotary square tube-4/12.7*565.2		1
4	R24101587404	158Torque tube-4/Φ 22*458.6		1
5	R24101587204	158Stabilizing tube-4/Φ 22*441.8		1
6	R24101587405	158Torque tube/Φ 22*484		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator—L		1
11	R21301582000	158Activator—R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007604	Bottom linkage-4-Φ 22*489		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1

















S. N	Part. No	Description	Pthoto	Qty
	R32015805101	450pounds Zerowall 158-5		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585005	Rotary square tube-5/12.7*590.6		1
4	R24101587405	158Torque tube-5/Φ 22*484		1
5	R24101587205	158Stabilizing tube-5/Φ 22*467.2		1
6	R24101587406	158Torque tube/Φ 22*509.4		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator—L		1
11	R21301582000	158Activator—R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007605	Bottom linkage-5-Φ 22*514.4		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1

S. N	Part. No	Description	Pthoto	Qty
	R32015806101	450pounds Zerowall 158-6		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585006	Rotary square tube-6/12.7*616		1
4	R24101587406	158Torque tube-6/Φ 22*509.4		1
5	R24101587206	158Stabilizing tube-6/Φ 22*492.6		1
6	R24101587407	158Torque tube/Φ 22*534.8		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator—L		1
11	R21301582000	158Activator—R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007606	Bottom linkage-6-Φ 22*539.8		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1

S. N	Part. No	Description	Pthoto	Qty
	R32015807101	450pounds Zerowall 158-7		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585007	Rotary square tube-7/12.7*641.4		1
4	R24101587407	158Torque tube-7/Φ 22*534.8		1
5	R24101587207	158Stabilizing tube-7/Φ 22*518		1
6	R24101587408	158Torque tube/Φ 22*560.2		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator—L		1
11	R21301582000	158Activator—R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007607	Bottom linkage-7-Φ 22*565.2		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1

S. N	Part. No	Description	Pthoto	Qty
	R32015808101	450pounds Zerowall 158-8		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585008	Rotary square tube-8/12.7*666.8		1
4	R24101587408	158Torque tube-8/Φ 22*560.2		1
5	R24101587208	158Stabilizing tube-8/Φ 22*543.4		1
6	R24101587409	158Torque tube/Φ 22*585.6		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator—L		1
11	R21301582000	158Activator—R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007608	Bottom linkage-8-Φ 22*590.6		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1

S. N	Part. No	Description	Pthoto	Qty
	R32015809101	450pounds Zerowall 158-9		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585009	Rotary square tube-9/12.7*692.2		1
4	R24101587409	158Torque tube-9/Φ 22*585.6		1
5	R24101587209	158Stabilizing tube-9/Φ 22*568.8		1
6	R24101587410	158Torque tube/Φ 22*611		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator—L		1
11	R21301582000	158Activator—R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007609	Bottom linkage-9-Φ 22*616		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1

S. N	Part. No	Description	Pthoto	Qty
	R32015810101	450pounds Zerowall 158-10		
1	R21101581000	158 Scissor without switch-LHF		1
2	R21101582000	158 Scissor without switch-RHF		1
3	R23101585010	Rotary square tube-10/12.7*717.6		1
4	R24101587410	158Torque tube-10/Φ 22*611		1
5	R24101587210	158Stabilizing tube-10/Φ 22*594.2		1
6	R24101587411	158Torque tube/Φ 22*636.4		1
7	R11011010003	Self-tapping screw-M7×23		2
8	R11011010001	Self-tapping screw M7×13		13
9	R11030000004	Red spring-Φ 17*Φ 2.0*175mm-52.25		2
10	R21301581000	158Activator—L		1
11	R21301582000	158Activator—R		
12	R12020000008	Mat-Nylon31*11MM		4
13	R11011010002	Self-tapping screw M7×18		8
14	R24100007610	Bottom linkage-10-Φ 22*641.4		2
15	R11080000002	KD sleeve-1.0		2
16	R12020000005	Black plastic square dragline		1