





















































































SN	Part. No.	Description	Pthoto	Qty
	R32358H00101	360pounds Zerowall 358H-0		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585000	Rotary square tube-0/12.7*463.6		1
4	R24106517300	Stabilizing tube-0/Φ 22*349.3		2
5	R24102587100	Torque tube-0/Φ 22*385.8		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-52.25		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator—L		1
12	R24100007600	Bottom linkage-0-Φ 22*387.4		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic Cable relaese		1















SN	Part. No.	Description	Pthoto	Qty
	R32358H01101	360pounds Zerowall 358H-1		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585001	Rotary square tube-1/12.7*489		1
4	R24106517301	Stabilizing tube-1/Φ 22*374.7		2
5	R24102587101	Torque tube-1/Φ 22*411.2		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-52.25		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator—L		1
12	R24100007601	Bottom linkage-1-Φ 22*412.8		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic Cable relaese		1















SN	Part. No.	Description	Pphoto	Qty
	R32358H02101	360pounds Zerowall 358H-2		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585002	Rotary square tube-2/12.7*514.4		1
4	R24106517302	Stabilizing tube-2/Φ 22*400.1		2
5	R24102587102	Torque tube-2/Φ 22*436.6		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-52.25		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator—L		1
12	R24100007602	Bottom linkage-2-Φ 22*438.2		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic Cable relaese		1















SN	Part. No.	Description	Pphoto	Qty
	R32358H03101	360pounds Zerowall 358H-3		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585003	Rotary square tube-3/12.7*539.8		1
4	R24106517303	Stabilizing tube-3/Φ 22*425.5		2
5	R24102587103	Torque tube-3/Φ 22*462		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-52.25		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator—L		1
12	R24100007603	Bottom linkage-3-Φ 22*463.4		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic Cable relaese		1















SN	Part. No.	Description	Pthoto	Qty
	R32358H04101	360pounds Zerowall 358H-4		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585004	Rotary square tube-4/12.7*565.2		1
4	R24106517304	Stabilizing tube-4/Φ 22*450.9		2
5	R24102587104	Torque tube-4/Φ 22*487.4		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-52.25		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator-L		1
12	R24100007604	Bottom linkage-4-Φ 22*489		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic Cable relaese		1















SN	Part. No.	Description	Pthoto	Qty
	R32358H05101	360pounds Zerowall 358H-5		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585005	Rotary square tube-5/12.7*590.6		1
4	R24106517305	Stabilizing tube-5/Φ 22*476.3		2
5	R24102587105	Torque tube-5/Φ 22*512.8		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-52.25		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator-L		1
12	R24100007605	Bottom linkage-5-Φ 22*514.4		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic Cable relaese		1

SN	Part. No.	Description	Pthoto	Qty
	R32358H06101	360pounds Zerowall 358H-6		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585006	Rotary square tube-6/12.7*616		1
4	R24106517306	Stabilizing tube-6/Φ 22*501.7		2
5	R24102587106	Torque tube-6/Φ 22*538.2		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-52.25		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator-L		1
12	R24100007606	Bottom linkage-6-Φ 22*539.8		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic Cable relaese		1

SN	Part. No.	Description	Pthoto	Qty
	R32358H07101	360pounds Zerowall 358H-7		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585007	Rotary square tube-7/12.7*641.4		1
4	R24106517307	Stabilizing tube-7/Φ 22*527.1		2
5	R24102587107	Torque tube-7/Φ 22*563.6		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-52.25		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator-L		1
12	R24100007607	Bottom linkage-7-Φ 22*565.2		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic Cable relaese		1

SN	Part. No.	Description	Pthoto	Qty
	R32358H08101	360pounds Zerowall 358H-8		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585008	Rotary square tube-8/12.7*666.8		1
4	R24106517308	Stabilizing tube-8/Φ 22*552.5		2
5	R24102587108	Torque tube-8/Φ 22*589		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-52.25		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator-L		1
12	R24100007608	Bottom linkage-8-Φ 22*590.6		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic Cable relaese		1

SN	Part. No.	Description	Pphoto	Qty
	R32358H09101	360pounds Zerowall 358H-9		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585009	Rotary square tube-9/12.7*692.2		1
4	R24106517309	Stabilizing tube-9/Φ 22*577.9		2
5	R24102587109	Torque tube-9/Φ 22*614.4		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator-L		1
12	R24100007609	Bottom linkage-9-Φ 22*616		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic square dragline		1

SN	Part. No.	Description	Pphoto	Qty
	R32358H10101	360pounds Zerowall 358H-10		
1	R211358H1000	358H Scissor-LHF		1
2	R211358H2000	358H Scissor-RHF		1
3	R23101585010	Rotary square tube-10/12.7*717.6		1
4	R24106517310	Stabilizing tube-10/Φ 22*603.3		2
5	R24102587110	Torque tube-10/Φ 22*639.8		1
6	R11011010003	Self-tapping screw-M7×23		2
7	R11011010001	Self-tapping screw-M7×13		13
8	R11030000004	Red sprin-Φ 17*Φ 2.0*175mm-		2
9	R12020000008	Mat-Nylon 31*11MM		4
10	R11011010002	Self-tapping screw-M7×18		8
11	R21301581000	Activator-L		1
12	R24100007610	Bottom linkage-10-Φ 22*641.4		2
13	R11080000002	KD Bracket-1.0		2
14	R12020000005	Black plastic square dragline		1